Notice

Model:



Effective from : Chassis No. P50747-05

CORRECTION	■ PRODUCTION CHAN	IGE	11111	
SERVICE FLASH	ADD INFORMATION		FILE NO.	
Please add this notic	REVISION 1			
Category: COLOR TELEVISION			FEBRUARY / 10 / 2010	

Destination: U.S.A. / CANADA REF : No. SM780156-05

NOTE: Match the Chassis No. on the unit's back cover with the Chassis No. in the Service Manual. If the Service Manual Chassis No. does not match the unit's, additional Service Literature is required. This chassis is similar to Chassis No. P50747-04. Only the difference Service Information is given in this manual. For detailed Service Information, refer to the Original Service Manual and Notices for Chassis No. P50747-04 used in Model DP50747 (SM780163-04).

SERVICING SHOULD BE PERFORMED BY ONLY TRAINED AND QUALIFIED SERVICE PERSONNEL.

1. IN THE SERVICE ADJUSTMENTS

DP50747

PAGE 4 ON-SCREEN SERVICE MENU

Item No. 088 OP2 Data should be changed from 14h to 29h in the table and in Note 2.

2. IN THE CHASSIS ELECTRICAL PARTS LIST MISCELLANEOUS

The reason for change.

A: Misprint B: Quality Reliability C: Standardization

D: Design E: Add as a possible sub F: Schematic location change

G: Purchasing Request

Page & Section	Schematic Location		Part No.	Description	Q'ty	Interchange- ability	Reason
Page 24, Chassis A101 Electrical Parts List	Δ101	Old	1AA0B10N238R0	ASSY, PWB, MAIN_A-J4DL	1	NO	. D
	7,101	New	1AA0B10N238U0	ASSY, PWB, MAIN_A-J4DLE	1	NO	
Page 16, Chassis Electrical Parts List	IC5500	Old	QXXAVC970M	IC 215-0619000-00	1	NO	- D
	100000	New	QXXAVC969M	IC 215-068400100	1	NO	

© Sanyo Manufacturing Corporation 2010

For parts or service contact:

Sanyo Manufacturing Corporation P.O. Box 2000 3333 Sanyo Road Forrest City, Arkansas 72335-2000

March 2010 SMC Published in Mexico